

**RAINFALL THRESHOLDS FOR THE
INITIATION OF SLOPE FAILURES AT
JELAPANG AND GUA TEMPURUNG AREA**

NORISAM BIN ABD RAHAMAN

**MASTER OF SCIENCE
UNIVERSITI PERTAHANAN
NASIONAL MALAYSIA**

2014

**RAINFALL THRESHOLDS FOR THE INITIATION OF SLOPE FAILURES
AT JELAPANG AND GUA TEMPURUNG AREA**

NORISAM BIN ABD RAHAMAN

Thesis Submitted to the Centre of Graduate Studies, Universiti Pertahanan Nasional
Malaysia, in Fulfillment of the Requirements for the Degree of Science (Civil
Engineering)

October 2014

ABSTRACT

For countries located near to the Equator Line, slope failures always associated with the presence of high volume of water due to heavy rainfall. The objective of the study was to find the rainfall threshold that potentially trigger slope failures. These thresholds were to be used as the trigger level to issue Warning Alert and Critical Alert in slope monitoring system. Two (2) study areas were selected i.e. Jelapang area and Gua Tempurung area, as both have substantially large catchments areas with steep natural slopes located beyond the Right-of-Ways (ROW) that feeds into the engineered slopes along the PLUS expressway although they depicted different geology and bedrock underlying the area. The development of Real Time Monitoring System (RTMS) was based on three (3) main elements i.e. complete field stations with sensors (site equipment), central database server and the medium of transmitting the field data to the server at Headquarters. Based on two (2) case studies for both areas and the analysis against rainfall data collected, slope failures occurred during/after rainfall event with intensity of more than 50mm/hour whereby this intensity can be used as the threshold for the RTMS to trigger Warning Alert.

ABSTRAK

Bagi negara-negara yang terletak berhampiran dengan Garisan Khatulistiwa, kejadian tanah runtuh biasa dikaitkan dengan banyaknya jumlah air hujan yang diterima ketika berlaku hujan lebat. Objektif kajian yang dijalankan adalah untuk mengenalpasti kadar atau jumlah hujan yang boleh menyebabkan berlakunya runtuh cerun di dalam kawasan kajian. Kadar atau jumlah hujan yang dikenalpasti, digunapakai bagi menentukan Amaran Awal ('Warning Alert') oleh Sistem Pemantauan Cerun. Dua kawasan kajian terlibat adalah kawasan Jelapang dan Gua Tempurung di Perak di mana kedua-dua kawasan kajian ini mempunyai saiz kawasan tadahan yang besar dengan cerun semulajadi walaupun keduanya mempunyai ciri-ciri geologi dan batuan hampar yang berbeza antara satu dengan lain. Sistem Pemantauan Masa Nyata ('Real Time Monitoring System - RTMS') dibangun berdasarkan tiga komponen penting iaitu stesyen di tapak pemantauan (peralatan tapak), pelayan pengkalan data serta kaedah penghantaran data dari tapak pemantauan ke pengkalan data. Berdasarkan kajian kes yang dijalankan di kedua-dua kawasan, kejadian runtuh cerun berlaku apabila kadar hujan yang turun melebihi 50mm/jam dan kadar ini boleh digunapakai sebagai had kadar hujan bagi amaran berjaga-jaga (Warning Alert).

ACKNOWLEDGEMENTS

My deepest gratitude to my advisor, Professor Dr. Faisal bin Haji Ali for his guidance, patience and understanding as well as his mentorship that pushed me forward up to this level. He was willing to be my supervisor despite of his other commitments either academic as well as professional commitments.

I would like to thank Universiti Pertahanan Nasional Malaysia (UPNM) for the platform given to me in elaborating my thought and presenting my ideas in this thesis. I would also like to thank Projek Lebuhraya Usahasama Sdn Bhd (PLUS) for allowing me to carry out data analysis and studies within PLUS area that enable me to fulfill the requirements.

I would also like to thank the following people as their support, patience and guidance had enable me to complete this thesis. And to them that I owe my deepest gratitude.

- My beloved wife, Puan Noor Hayate Mat Yusoff whose constant patience, understanding and encouragement had given me strength to complete the thesis.
- My children, Nur Alya Safiah, Muhammad Danish Iman and Qhayra Adelia Rania. This dissertation is dedicated to them for their future inspiration.

- Ir. Mohd. Zulastrı Mohd Amin, Hajah Norbayati Hj Manap and Hajjah Asmaniza Asanan whose guidance and encouragement given me strength to go forward.
- Friends and family members whose support and cooperation had enable me to complete the thesis.

APPROVAL

I certify that an Examination Committee has met on **13 October 2014** to conduct the final examination of **Norisam Bin Abd Rahaman** on his degree thesis entitled '**Rainfall Threshold for The Initiation of Slope Failures at Jelapang and Gua Tempurung Area**'. The committee recommends that the student be awarded the Master of Science.

Members of the Examination Committee were as follows:

Prof. Madya Dr. Azizi Bin Miskon
Universiti Pertahanan Nasional Malaysia
(Chairman)

Prof. Madya Ir. Dr. Mohammed Alias Bin Yusof
Universiti Pertahanan Nasional Malaysia
(Internal Examiner)

Prof. Dr. Bujang Kim Huat
Universiti Putra Malaysia
(External Examiner)

UNIVERSITI PERTAHANAN NASIONAL MALAYSIA

DECLARATION OF THESIS

Name : Norisam Bin Abd Rahaman
Date of birth : 22 May 1972
Title : Rainfall Threshold For The Initiation Of Slope Failures At Jelapang And Gua Tempurung Area
Academic session : 2012 - 2014

I declare that this thesis is classified as:

- CONFIDENTIAL** (Contain confidential information under the Official Secret Act 1972)
- RESTRICTED** (Contain restricted information as specified by the organization where research was done)
- OPEN ACCESS** I agree that my thesis to be published as onlines open access (full text)

I acknowledge that Universiti Pertahanan Nasional Malaysia reserves the right as follows.

1. The thesis is the property of Universiti Pertahanan Nasional Malaysia.
2. The library of Universiti Pertahanan Nasional Malaysia has the right to make copies for the purpose of research only.
3. The library has the right to make copies of the thesis for academic exchange.

NORISAM BIN ABD RAHAMAN
720522-01-5759

PROF. DR. FAISAL BIN HJ. ALI

DATE:

DATE:

TABLE OF CONTENTS

	Page
ABSTRACT	ii
ABSTRAK	iii
ACKNOWLEDGEMENTS	iv
APPROVAL	vi
DECLARATION	vii
TABLE OF CONTENTS	viii
LIST OF TABLES	x
LIST OF FIGURES	xi
LIST OF ABBREVIATIONS	xii
CHAPTER	
1 INTRODUCTION	1
1.1 General Overview	1
1.2 Background of the Study	3
1.3 Problem Statement	7
1.4 Objectives of Research	8
1.5 Scope of Research	8
1.6 Limitations	10
2 THEORY AND LITERATURE REVIEW	11
2.1 Introduction	11
2.2 Rainfall	14
2.3 Slopes	16
2.3.1 Natural Slopes vs. Engineered Slopes	16
2.3.2 Failure Modes	18
2.4 Literature Review of Previous Studies	20
2.5 Real Time Monitoring System	25
3 METHODOLOGY	26
3.1 Introduction	26
3.2 Proposed Location of Study	27
3.2.1 Geography and Geology of Jelapang Area	29
3.2.2 Geography and Geology of Gua Tempurung Area	32
3.3 Proposed Monitoring System	34
3.3.1 Conceptual layout	35
3.3.2 System Installation	37
3.3.2.1 Field Stations	37
3.3.2.2 Server System	40
3.3.2.3 Data Transmission	41
3.3.3 System Performance	42

3.4	Data Collection	43
3.4.1	Catchment Area	44
3.4.2	Failure Records	48
3.4.3	Rainfall Data Collection	48
3.4.4	Case study	50
4	DATA ANALYSIS AND RESULTS	52
4.1	Introduction	52
4.2	Slope Failure Records	52
4.2.1	Records of slope failures within Jelapang	53
4.2.2	Records of slope failures within Gua Tempurung	56
4.3	Rainfall Trends and Analysis	59
4.3.1	Rain-gauge Installation for Jelapang and Gua Tempurung	60
4.3.2	Annual Rainfall Analysis	63
4.3.3	Monthly Rainfall Analysis	65
4.3.4	Daily and Hourly Rainfall	73
4.4	Analysis of Catchments Areas	74
4.4.1	GIS Analysis for Jelapang Area	76
4.4.1.1	Slope Aspect Analysis	77
4.4.1.2	Slope Angle Analysis	78
4.4.1.3	Curvature Analysis	79
4.4.1.4	Hydrology Analysis	81
4.4.1.5	Elevation Analysis	81
4.4.2	GIS Analysis for Gua Tempurung Area	83
4.4.2.1	Slope Aspect Analysis	83
4.4.2.2	Slope Angle Analysis	84
4.4.2.3	Curvature Analysis	85
4.4.2.4	Hydrology Analysis	85
4.4.2.5	Elevation Analysis	86
4.4.3	Frequency Ratio Analysis	87
4.5	Analysis for Rainfall Threshold	90
4.5.1	Case study for Jelapang	91
4.5.2	Case study for Gua Tempurung	95
5	DISCUSSION	104
5.1	Introduction	104
5.2	Analysis of Catchments Against Records of Slope Failures	106
5.3	Rainfall Trends Analysis	110
6	CONCLUSION	120
6.1	System Installation and Rainfall Pattern	120
6.2	Records of slope failures in Jelapang and Gua Tempurung	122
6.3	Rainfall Threshold	122

REFERENCES	124
LIST OF APPENDICES	
A - Flowchart for the research methodology	128
B - Rainfall data for Jelapang area (January – April 2011)	130
C - Rainfall data for Gua Tempurung area (January – April 2012)	139
D - GIS Analysis for Jelapang area	148
E - GIS Analysis for Gua Tempurung area	154
F - Case study for Jelapang	160
G - Case study for Gua Tempurung	174
BIODATA OF STUDENT	188

LIST OF TABLES

TABLE NO.	DESCRIPTION	PAGE
2.1	Water infiltration rate in different grades of soil	24
4.1	Location of rain-gauge stations along Jelapang stretch.	61
4.2	Location of Rain Gauge Stations along Gua Tempurung stretch	62
4.3	Comparison of annual rainfall data for Year 2011 and Year 2012 for Jelapang area	64
4.4	Comparison of annual rainfall data for Year 2011 and Year 2012 for Gua Tempurung area	65
4.5	Monthly rainfall for Jelapang Area (Year 2011)	66
4.6	Monthly rainfall for Jelapang Area (Year 2012)	67
4.7	Monthly rainfall for Gua Tempurung Area (Year 2011)	70
4.8	Monthly rainfall for Gua Tempurung Area (Year 2012)	71
4.9	Analysis for slope failure data against slope aspects within Jelapang area	78
4.10	Slope failure data against slope angles for Jelapang	78
4.11	Slope failure data against surface curvature for Jelapang	80
4.12	Slope failure data against ground elevation for Jelapang	82
4.13	Slope aspects analysis for Gua Tempurung	84
4.14	Slope angle analysis for Gua Tempurung	85
4.15	Surface curvature analysis for Gua Tempurung	85
4.16	Slope failure data against ground elevation for Gua Tempurung	86
4.17	Frequency Ratio Analysis for slope inclination	88
4.18	Frequency Ratio Analysis for slope aspects	89
4.19	Frequency Ratio Analysis for surface elevation	89
4.20	Daily rainfall trend for Month of April 2011 for RGN5-1	93
4.21	Daily rainfall trend for Month of April 2011 for RGN5-3	94
4.22	Distance of slope failures from rain-gauges installed	97
4.23	Monthly rainfall for Gua Tempurung area	98
4.24	Comparison of daily rainfall trends amongst rain-gauges installed within Gua Tempurung area (6 April – 13 April 2012)	99
4.25	RGC1-4 shows hourly rainfall trends for Month of April 2012	100
4.26	First cycle rainfall distribution within Gua Tempurung area	101
4.27	Second cycle rainfall distribution within Gua Tempurung area	102
4.28	Rainfall data from Meteorological Department of Malaysia and rainfall data at Gua Tempurung area	103
5.1	Summary of catchment analysis based on slope failure records	109
5.2	Annual rainfall comparison for Jelapang and Gua Tempurung	110
5.3	Monthly rainfall distribution for Jelapang and Gua Tempurung	112
5.4	Comparison of cumulative monthly rainfall for April 2011 and April 2012 for both locations	113
5.5	Average of precipitation at Jelapang on 23 April 2011	117
5.6	Hourly rainfall data for Gua Tempurung on 11 and 12 April 2012	118
6.1	Highest rainfall intensity recorded in relation to slope failures occurred	122

LIST OF FIGURES

FIGURE NO.	DESCRIPTION	PAGE
1.1	Alignment of the Expressways under PLUS	4
2.1	Mohr-Coulomb failure criterion formula for unsaturated soils	22
3.1	Aerial photo of Jelapang area with the expressways coming from the south	30
3.2	Aerial photo of Gua Tempurung area (facing north)	33
3.3	General concept of RTMS system operations	36
3.4	Typical layout of rain-gauge station.	39
4.1	Locations of slope failures (within and outside of ROW) were plotted on the DTM of Jelapang Area	55
4.2	Locations of slope failures (within and outside of ROW) were plotted on the DTM of Gua Tempurung Area	58
4.3	Map showing location of rain-gauge stations within Jelapang area with the ground terrain	61
4.4	View of Rain-Gauge Stations at Gua Tempurung area with the ground terrain	63
4.5	Diagram of Concave and Convex surfaces	79
4.6	Formula for Frequency Ratio	88
4.7	Photo of slope failure occurred at Km259.95 SB	92
4.8	Several slope failures observed during an aerial inspection	96
4.9	Slope failures observed during aerial inspection	96
5.1	Daily rainfall distribution for April 2011 (RGN5-3 and RGN5-1)	115
5.2	Hourly rainfall distribution for 23 April 2011 (one day before the slope failure)	116

LIST OF ABBREVIATIONS / GLOSSARY / TERMS

2G	Second Generation (Wireless telephone technology)
3G	Third Generation (Wireless telephone technology)
BB	Both Bound
DID	Drainage and Irrigation Department
DEM	Digital Elevation Model
DSM	Digital Surface Model
DTM	Digital Terrain Model
GIS	Geographical Information System
GPRS	General Packet Radio Services
GSM	Global System for Mobile Communication
GUI	Graphical User Interface
HQ	Head Quarters
ID	Identification
IFSAR	Interfero-metric Synthetic Aperture Radar
MHA	Malaysian Highway Authority
MySQL	'My' - Structured Query Language
NB	North Bound (travelling from South to North)
NSE	North-South Expressway
NSMP	National Slopes Master Plan
NW-SE	North West – South East
PLUS	Projek Lebuhraya Usahasama Berhad
R.O.W.	Right-of-Way
RTMS	Real Time Monitoring System
SAR	Synthetic Aperture Radar
SB	South bound (travelling from North to South)
SIM Card	Subscriber Identification Module card
TCP/IP	Transmission Control Protocol / Internet Protocol
TEMAN	Total Expressway Maintenance Management

CHAPTER 1

INTRODUCTION

1.1 General Overview

This chapter deals with the overview of rainfall induced slope failures, the system layout for the Real Time Monitoring System (RTMS), the study areas, as well as the process of determining rainfall threshold for any rainfall induced slope failure to occur. The research looked into rainfall data collected using rain-gauges installed within study areas and analysis of rainfall pattern. Data of slope failure records that occurred in the past, within the study areas were also analyzed. And case studies were carried out to determine the threshold level for rainfall to trigger a slope failure. This threshold rainfall level was used to indicate the point for triggering warning alerts to engineers who were responsible for carrying out further investigation on site.

Two (2) focus areas were selected that have substantially large catchments areas located beyond the Expressway's Right-of-Way (ROW). In case of any major slope failure or debris flow occurred within these upstream catchments areas, it will have potential impact towards the Expressway that may cause damages and dangerous to road users. This research also looked into the connection between slope failures occurred within selected study areas and the rainfall received throughout the year within the areas.

Slope failures were common around the world especially in wet tropical region like the South-East Asia. Slope failures were often associated with the rainfall and statistically analyzed with the total amount and/or the intensity of rainfall (Katsuyuki, 1999). Rainfall induced slope failures of unsaturated residual soil slopes occurred when there was an increase in moisture content and a decrease in soil matric suction (Krahn et al, 1989; Lambe, 1996)

Slope failures at hilly terrain can be triggered by many external and internal factors such as earthquake tremors, intense rainfall and stream erosion. These factors can cause increases in the driving shear forces and decreased the existing shear strength of the slope. There were also other long term factors that affecting slope stability such as vegetation covers, drainage conditions, climate and weathering as well as human activities which may lead to slope failures.

Slope failures were the major concern to the Government and the people due to the extent of damages it caused as well as casualties and losses that the people suffered when slope failures occurred. Furthermore, slope failures can lead to economic losses to the country. Despite the efforts of preventing slope failures and mitigating losses due to slope failures, many were caught off-guard when slope failures occurred as there was still no clear indicative threshold that can trigger warning to engineers with regards to potential slope failure.

1.2 Background of the Study

Expressways were built to connect people of an area with other regions, either near or far. Expressways were constructed and maintained to promote economic development as well as commercial activities, to move people and goods around thus facilitating planned and sustainable urban growth.

The North-South Expressway (NSE) was managed by Projek Lebuhraya Usahasama Berhad (PLUS Berhad) formerly known as Projek Lebuhraya Utara-Selatan (PLUS), a subsidiary of UEM Berhad. As the major expressway service operator, PLUS also managing other expressways in Peninsular Malaysia including:

- a) The North-South Expressway (NSE) network consists of Expressway Route Number E1, stretching from Bukit Kayu Hitam to Jalan Duta inclusive of the New Klang Valley Expressway (Jalan Duta – Bukit Raja) as well as Federal Highway Route 2. Whereas, at the southern part, the NSE consists of Expressway Route Number E2 stretching from Sungai Besi Toll Plaza to Kempas Toll Plaza in Johor.
- b) The North-South Expressway Central Link (ELITE) from Shah Alam Interchange to Nilai Utara Interchange. This expressway linking up both E1 and E2 of the NSE.
- c) The Butterworth – Kulim Expressway (BKE)

- d) Malaysia – Singapore Second Crossing (MSSC) from Senai Utara Interchange to Tanjung Kupang in Johor before crossing the Strait of Johor via the MSSC Bridge and landed at Tuas in Singapore.
- e) Penang Bridge connecting Butterworth area at the mainland of Peninsular Malaysia and Minden at Penang Island.




Figure 1.1: Alignment of the Expressways under PLUS (Source from www.plus.com.my)

Figure 1.1 shows the alignment of the North-South Expressway as well as other Expressways under management of PLUS Berhad.

Expressways were designed such that to ease travelling of road users from one place to another. The North-South Expressway (NSE) was built to connect major cities along its route from Bukit Kayu Hitam at the North to Johor Bahru at the South. Therefore, the expressways had been constructed through different terrain from the north of Peninsular Malaysia to the southern tip of Peninsular Malaysia.

While going through different terrains and ground altitudes, the longitudinal gradient have to be kept at the most minimum gradient for safety, riding comfort as well as vehicle control. In order to achieve this with the most optimum construction cost, the expressways were constructed via cut and fill method along the given alignment where the expressway have to cut into hills and mountains as well as crossing valleys on fill embankments. This method of construction resulted in various kind of cut and fill slopes despite other man-made structures forming the expressways mainline i.e. embankments, bridges and tunnels.

Different terrain and geography were observed throughout the expressway's alignment. Flat terrain and soft ground were observed within Kedah and Seberang Perai where the expressway traversing through vast paddy fields. Within the soft ground area where the geology mainly consists of soft marine clay, the expressways were built at minimum embankment height, coupled with several foundation treatments to strengthen the base.

Mountainous terrain were observed within the route in Perak i.e. Jelapang area and Gua Tempurung area. Within Jelapang area, the expressway cut into the rock mass / bed rock while travelling the side terrain of the mountain range before going through tunnels at the highest point. Here, the man-made slopes were consists of high rock cut slopes with shallow soil slope on top. While at Gua Tempurung, the expressway cut through deep regolith / soil mass resulting in high cut soil slopes.

Hilly undulating terrains were observed along the side of the expressway while travelling through majority of Perak, Selangor, Negeri Sembilan, Melaka and Johor area. Within these areas, the expressway was built on cut and fill embankment, thus creating many cut slopes and embankment slopes along the way.

In order to ensure the expressways were secured at all time, these man-made slopes along the expressways were properly monitored, maintained and up-kept. With a vast number of slopes along the expressways, it was unknown which slope going to fail or when a major slope failure may occur. Once a major slope failure occurred, it required huge cost of repair in order to restore the slope to its original condition or to enhance the slope with better engineering solution and stabilization method. Slope failures that affecting an expressway will disrupt major economic supply line and might also involve potential loss of life as well as the victim's economic value.

Monitoring the prominent and active elements that can cause slope failures such as rainfall volume and its intensity, will prepare the Highway Operator to act on the counter measures necessary to prevent or control the potential failures, or at least minimizing the impact for the safety of road users and other expressway's assets in

case of unavoidable slope failure. Therefore, it was necessary to have a threshold level for the rainfall as trigger points in issuing warning alert that lead to further necessary action.

1.3 Problem Statement

As Malaysia is located near the Equator Line, it experiences high volume of rainfall as well as a lot of heat from the sun throughout the year. In this wet tropical region, Malaysia experiences high degree of weathering processes and activities in the form of mechanical weathering as well as chemical weathering.

General observation on several slope failures occurred in Malaysia and several other areas around the globe, slope failures normally occurred after certain period of heavy and prolong rainfall or heavy thunderstorms. However, there was no clear indication of any rainfall volume and intensity that can trigger a slope failure.

1.4 Objectives of the Research

Three (3) objectives were identified for the research:

- a) To study rainfall pattern for Jelapang and Gua Tempurung area and to identify wet seasons for the areas
- b) To study trends of slope failures in mountainous region in Jelapang and Gua Tempurung areas.
- c) To determine the threshold of rainfall volume/intensity that could cause slope failures or debris flow within the upper catchments of Jelapang and Gua Tempurung areas.

1.5 Scope of Research

The scope of study for the research can be divided into three (3) major activities. These will involve the following:

- a) The research focused on two (2) mountainous regions within the North-South Expressway i.e. Jelapang area and Gua Tempurung area. These areas of concerned located at mountainous region in which large upstream catchments area were formed beyond the expressway's Right-of-Way (R.O.W). The catchments study was carried out based on Interferometric Synthetic Aperture

Radar (IFSAR) data of the respective regions. These involved the processing of raw IFSAR data and satellite images to generate Digital Elevation Model (DEM) using ERDAS Imagine software. The DEM was then processed and analyzed using ArcGIS Software for the slope aspects, slope angle, slope curvature, elevation and hydrology analysis. Based on several major defects and slope failure records obtained from PLUS, comparison and analysis were carried out against the GIS analysis of the catchments area. The ratio analysis indicates which quadrants of catchments areas were susceptible to slope failure.

- b) The research also explored the development of Real Time Monitoring System (RTMS) in which the rainfall data recorded on site were transmitted in real time to the Central Server located at PLUS Headquarters for analysis. Based on the rainfall data collected, analysis for rainfall trends were carried out for hourly rainfall, daily rainfall, monthly rainfall as well as annual rainfall. For this study, rainfall analyzed was from the data collected in Year 2011 and 2012.
- c) A case study for each area at Jelapang and Gua Tempurung were used to determine the threshold of rainfall that triggered the slope failures. Cross references were carried out with reports on unusual rainfall and flooding from Meteorological Department of Malaysia.

1.6 Limitations

There were many factors that contributed in causing slope instability. This field of research will focus on the effect of rainfall as the main variable over time while other preparatory factors were assumed to be constant.

Verification were based on slope failures recorded by PLUS. However, since the rainfall data collection started from January 2010, while the records of slope failures can be traced back from the time before data collection being activated, there were limitation in comparing the rainfall data and slope failures occurrence in these regions.

CHAPTER 2

THEORY AND LITERATURE REVIEW

2.1 Introduction

Slope failures were one of the hot topics being discussed amongst civil engineers and geotechnical engineers around the globe. Slope failures can occur as long as there were slopes around the area, either engineered slopes constructed by human or natural slopes. Slope failures can be in the form of small scale and localized failures or massive failures and regional in nature. Some of the slope failures may traveled down the terrain if the condition permitted in a form of debris flow, damaging the adjacent populated area that normally located downstream. And for the case of roads or expressways, the damages can cause major disruptions to the trunk line that causing economic loses over a period of time before clearing and rehabilitation works being carried out.

There were many types of slope failures, depends on the properties of soil within the affected areas such as rotational, transitional and rock fall. In addition, there were also many factors that can trigger slope failures such as earthquake, rainfall as well as deterioration due to weathering process.